


FIG. 1

FIG. 2

_100






FIG. 3




FIG 4

FIG. 5




FIG. 6

CMD PR PWRITE 22 24 PWR

CNTSTOP

20ر

FIG. 7





FIG. 8



40

FIG. 9




FIG. 10

200

FIG. 11

POWER_UP 302
303
304
305
PtWR1 (PtWR2,PtWR3)
VSS




FIG. 12